

Telemecanique Emergency stop rope pull switches XY2C, turnbuckle M6, for XY2C



XY2CZ402

| Range of product | Telemecanique Emergency stop rope pull switches XY2C |
|---------------------------------------|--|
| Accessory / separate part designation | Turnbuckle M6 x 60 with locknut |
| Accessory / separate part type | Turnbuckle |
| Accessory / separate part category | Separate parts |
| Accessory / separate part destination | Emergency stop rope pull switch |

Complementary

| Product compatibility | XY2CE XY2CJ |
|-----------------------|----------------|
| Length | 60 mm |
| Net weight | 0.06 kg |

Packing Units

| r doming office | |
|------------------------------|----------|
| Unit Type of Package 1 | PCE |
| Number of Units in Package 1 | 1 |
| Package 1 Weight | 74.0 g |
| Package 1 Height | 1.0 cm |
| Package 1 width | 17.0 cm |
| Package 1 Length | 6.0 cm |
| Unit Type of Package 2 | S01 |
| Number of Units in Package 2 | 60 |
| Package 2 Weight | 4.701 kg |
| Package 2 Height | 15.0 cm |
| Package 2 width | 15.0 cm |
| Package 2 Length | 40.0 cm |
| | |

Offer Sustainability

| Sustainable offer status | Green Premium product |
|--------------------------|-----------------------|
| REACh Regulation | REACh Declaration |

| EU RoHS Directive | Pro-active compliance (Product out of EU RoHS legal scope) EU RoHS Declaration |
|----------------------------|---|
| Mercury free | Yes |
| RoHS exemption information | Yes |
| Environmental Disclosure | Product Environmental Profile |
| California proposition 65 | WARNING: This product can expose you to chemicals including: Diisononyl phthalate (DINP), which is known to the State of California to cause cancer, and Di-isodecyl phthalate (DIDP), which is known to the State of California to cause birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov |
| Contractual warranty | |

18 months

Warranty