





Plug in relay, flange mounted, DPDT, 10 amp at 277 VAC, 24 VDC coil

8501KFDR12V53

! Discontinued on: Jan 23, 2021

! Discontinued

Main

Product Range	8501K
Product Type	Relay
Relay Type	General purpose
Mounting Type	Flange
Contact Composition	DPDT
Manual Operator	Without test button

Complementary

Horsepower Rating	1 hp 277 V AC	
Maximum Switching Voltage	300 V AC 30 V DC	
Contact Material	Silver alloy (AgNi)	
Operating Time	20 ms - pick-up 20 ms - drop-out	
Shape Of Pins	Spade	

Environment

Ambient Temperature Range - Operational	-40131 °F (-4055 °C)
Product Certifications	UL Recognized CSA CE
Height	2.75 in (69.85 mm)
Width	1.4 in (35.56 mm)
Depth	1.4 in (35.56 mm)

Ordering and shipping details

Category	21145-8501 KF,KL
Discount Schedule	CP2
Gtin	00785901984412
Returnability	No
Country Of Origin	CN

Price is "List Price" and may be subject to a trade discount – check with your local distributor or retailer for actual price.

Sustainability Green Premium

Green PremiumTM **label** is Schneider Electric's commitment to delivering products with best-inclass environmental performance. Green Premium promises compliance with the latest regulations, transparency on environmental impacts, as well as circular and low-CO₂ products.

Guide to assessing product sustainability is a white paper that clarifies global eco-label standards and how to interpret environmental declarations.

Learn more about Green Premium >

Guide to assess a product's sustainability >





Transparency RoHS/REACh

Well-being performance



Reach Free Of Svhc



Rohs Exemption Information

Yes

Certifications & Standards

Reach Regulation	REACh Declaration
Eu Rohs Directive	Pro-active compliance (Product out of EU RoHS legal scope) EU RoHS Declaration
China Rohs Regulation	China RoHS declaration
Environmental Disclosure	Product Environmental Profile
Circularity Profile	No need of specific recycling operations
California Proposition 65	WARNING: This product can expose you to chemicals including: Nickel compounds, which is known to the State of California to cause cancer, and Di-isodecyl phthalate (DIDP), which is known to the State of California to cause birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov